



U. S. Steel  
Clairton Works  
400 State Street  
Clairton, PA 15025-1855

October 3, 1996

Director  
Air Toxics and Radiation Division  
U. S. EPA, Region III  
841 Chestnut Street  
Philadelphia, PA 19107

SUBJECT: 1996 Summary Report - Leak Detection and Repair of  
Equipment in Benzene Service

Dear Mr. Sir or Madam:

Enclosed, please find two copies of the following benzene NESHAPS monitoring report:

- Leak Detection and Repair of Equipment in Benzene Service for the  
Period January 1, 1996 through June 1996.

This report summarizes the results of the monitoring of equipment in benzene service at  
USS Clairton Works for fugitive emissions. The report has been prepared to satisfy the  
requirements promulgated by 40 CFR 61 Subparts L and V.

If you have any questions regarding this package, please call me at (412) 233-1101.

Sincerely,

A handwritten signature in cursive script, reading "H. R. McCollum".

H. R. McCollum  
Manager, Environmental Control

HRM/kb-96229  
Enclosures

